

SECRET

Declassification Review by NGA/DoD

S E C R E T 012003Z

1965 JUN 1 20 23Z

OUT55870

25X1

1. CAMERA B 122 WAS USED IN MISSION 8019 FLOWN ON 27 MAY 1965. PROCESSING WAS ACCOMPLISHED BY BARKSDALE.

2. ORIGINAL NEGATIVE:

A. THE EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD.

B. 9R SIDE: MINOR STATIC DISCHARGES ARE PRESENT ON BOTH EDGES THROUGHOUT THE FILM. THE OUTBOARD EDGE ALSO CONTAINS INTERMITTENT EDGE FOGGING. A MANUFACTURER'S SPLICE IS POSITIONED WITHIN THE FORMAT OF FRAME 244. 2 JUN 1965

C. 9L SIDE: MINOR STATIC DISCHARGES AND INTERMITTENT EDGE FOGGING ARE PRESENT ON BOTH EDGES. FRAMES 3 TO 86 CONTAIN 2 ROWS OF MINUS DENSITY SPOTS IMMEDIATELY ADJACENT TO THE OUTBOARD EDGES OF THE FORMATS. THE SPOT-TO-SPOT SPACING IS 1.7". FRAMES 258 TO 860 AND 898 ARE DEGRADED BY FOG THAT ENTERS THE FORMATS OVER THE OUTBOARD EDGE OF THE FILM. SIMILAR DEGRADATION IS PRESENT IN FRAMES 879, 880, 862 AND 863 BUT THE FOG ENTERS ACROSS THE INBOARD EDGE OF THE FILM. FRAME 682 CONTAINS A MANUFACTURER'S SPLICE.

D. BOTH SIDES: THE TITLED FRAMES ARE NUMBERED 0000 TO 2352.

E. THERE WERE NO MAJOR CAMERA MALFUNCTIONS OR PROCESSING ANOMALIES.

COPIES RECEIVED 7		
Cy No.	Office	Act.
	File	
	OS	
	ADMIN	
	SEC BR	
	P&DS	
	CSD	
	IPD	
	PD	
	PSD	
	PSD-ICB	
3, 4	TID	<input checked="" type="checkbox"/>
	PID	
	PAG	
	DIAXX-4	
	SPAD	
	NSA-LO	
	DIA-AP	

3. POSITIVE:

A. THE PI SUITABILITY IS GOOD.

B. PRINTING AND PROCESSING ARE GOOD.

C. CLOUDS OBSCURE 25 PERCENT OF THE TERRAIN COVERED IN THIS MISSION.

S E C R E T

--END OF MESSAGE--

GROUP 1
Excluded from automatic
downgrading and
declassification